



Dart Hawkesbury
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

D3800-1-100-300
Job Sheet 168626



Part No: D3800-1-100-300

Job Qty: 10 ea

Part Name: Hook And Loop Strip (1" Soft) - 30" long



Part Weight: 0 lbs

Status: Scheduled

Priority: High

Job Created: 11/20/17

Job Tracking No:

Due Date: 11/21/17

Created By: Mario Poulin

Type: SOLD

Description:

Customer: Metro Aviation Inc (CMETR01)

PO Box 7008 Shreveport, LA, 71137 USA ph:(318) 222-5529 fx:(318) 698-5205.

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	10 Ea		11/20/17	0.00	0.00	Start Up Small Fab-4		17-11-2017 38 9-08 NOV 21 2017
100	Small Fab	10 pcs		11/21/17	0.00	0.50	Small Fab-9		
110	QC	10 pcs		11/21/17	0.00	0.00	QC5		
120	Packaging	10 pcs		11/21/17	0.00	0.00	Packaging3-2 PKG		
130	QC21-SA	10 Ea		11/21/17	0.00	0.00	QC21		

Part Op Descriptions: 100 - CUT TO 30.00" AS PER DWG

Job Allocations

Operation	Component Part	Required	Inventory	Allocated	Std Qty
90-Start up Operation	D3800-1-100	25	215	0	0

Part Specifications

Specifications could not be found.

Plex 11/20/17 11:54 AM dart.poulin.mario

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Suspected Un		AGAINST DEPARTMENT/PROCESS ☐ Cross tube ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Store/Packaging Supplier ☐ Engineering ☐ Quality ☐ Other							
Date : _____		Step #: _____		MRB (QS1042) Approval							
Description Work Order Deviation				Completed By							
				Lead hand / Supervisor Approval Verification							
				QC / QA Coordinator Approval							
Root Cause <table style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%; vertical-align: top;"> Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ </td> <td style="width:50%; vertical-align: top;"> No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐ </td> </tr> </table>		Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	<table style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%; vertical-align: top;"> Pressu ☐ Bendi ☐ Centr ☐ Crack ☐ Crin ☐ Cuf ☐ Cri ☐ He ☐ Wave/Twist in ☐ Marks/Chatter ☐ </td> <td style="width:50%; vertical-align: top;"> Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mis-labeled ☐ Fit/Function ☐ Misaligned/off center ☐ </td> </tr> </table>		Pressu ☐ Bendi ☐ Centr ☐ Crack ☐ Crin ☐ Cuf ☐ Cri ☐ He ☐ Wave/Twist in ☐ Marks/Chatter ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mis-labeled ☐ Fit/Function ☐ Misaligned/off center ☐	<table style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%; vertical-align: top;"> Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐ </td> <td style="width:50%; vertical-align: top;"> OTHER : ☐ </td> </tr> </table>		Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	OTHER : ☐
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐										
Pressu ☐ Bendi ☐ Centr ☐ Crack ☐ Crin ☐ Cuf ☐ Cri ☐ He ☐ Wave/Twist in ☐ Marks/Chatter ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mis-labeled ☐ Fit/Function ☐ Misaligned/off center ☐										
Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	OTHER : ☐										

PART NO:
 Revision:
 Operation:
 Change No:

Start up Operation
 D3800-1-100-300

Mfg Date: 11/20/17
 Job No: 168626

Hook And Loop Strip (1" Soft) - 30" long

DART Aerospace Ltd.
 1270 Aberdeen Street
 Hawkesbury, ON K6A 1K7
 TEL: 1 613 632-5200
 Email: sales@dartaero.com
 www.dartaerospace.com